

The hazardous waste codes approved and accepted at the facility is listed below. Wastes are received in accordance with the Waste Analysis Plan and analytical protocols. All shipments received are sampled, analyzed, and approved by the laboratory and all accompanying paperwork is checked for accuracy and compliance before off – loading occurs. If necessary, outside or other laboratories are available to supplement local analytical capabilities.

The facility is instituting OSHA’s Process Safety Management (PSM) program and the Chemical Manufacturer’s Association “Responsible Care” program.

**Disposal Waste Codes**

Waste Express, Inc. Acceptable Waste Codes January, 2008

D001	D002	D003	D004	D005	D006
D007	D008	D009	D010	D011	D012
D013	D014	D015	D016	D017	D018
D019	D020	D021	D022	D023	D024
D025	D026	D027	D028	D029	D030
D031	D032	D033	D034	D035	D036
D037	D038	D039	D040	D041	D042
D043	D098*				
F001	F002	F003	F004	F005	F006
F012	F019	F024	F025	F032	F034
F035	F037	F038	F039		
K001	K002	K003	K004	K005	K006
K007	K008	K009	K010	K015	K016
K017	K018	K019	K020	K022	K023
K024	K025	K026	K027	K028	K029
K030	K032	K033	K034	K035	K036
K037	K048	K049	K050	K051	K052
K060	K083	K085	K086	K087	K088
K093	K094	K095	K096	K103	K104
K105	K106	K108	K109	K111	K112
K113	K114	K115	K116	K117	
U002	U003	U007	U012	U019	U021
U023	U024	U025	U027	U031	U037
U038	U039	U043	U044	U045	U047
U048	U050	U051	U052	U053	U055
U056	U057	U069	U070	U071	U072
U073	U074	U075	U076	U077	U078
U079	U080	U081	U082	U083	U092
U101	U105	U106	U110	U112	U113

U114	U117	U118	U121	U122	U124
U125	U128	U131	U133	U138	U140
U143	U144	U145	U154	U155	U157
U158	U159	U161	U162	U165	U168
U170	U183	U184	U186	U188	U190
U194	U196	U201	U207	U208	U209
U210	U211	U213	U220	U221	U223
U225	U226	U227	U228	U236	U238
U239	U240	U247	U249	U274	U279
U359	U409	U411			

\* Designated Missouri Waste Codes